Report: February 2007

Date of work: Feb. 2007

# Repair & reinforcement of the water pipe in Tokyo

600mm dia. Iron pipe, pressure approx.0.5Mpa. Straight portion 1, elbow and straight portion each 1, reinforcement approx.2meter long

#### 1. Elbow



1). First, clean off the dirts with wes to check the pipe condition. Found out a few corrosion spots and 1 leak spot



3 Apply Magicawarp-Steel on the edge of the piping for reinforcement



(5) Then, wrap the Magicawrap for anticorrosion, protection and reinforcement to

squeeze for 1-2 minutes at the same direction.



②apply and fill Magicawrap-Steel on the dents caused by corrosion.



Then, apply Butyl Roll entirely as pretreatment of Magicawrap, and put Magicawarpseal on the edge of the piping for safety

#### Materials used:

- Magicawrap-Steel
- Butyl Roll
- •Magicawrap-Seal
- Magicawrap

### II Leak spot



**6** water is running on 1 spot due to the corrosion



**®**Then, wrap the Magicawrap and squeeze 1-2 minutes at the same direction.

## **Ⅲ** Straight portion





On the sopt, wrap the Butyl roll, and then Magicawrap-tape to stop leak

Materials used: Butyl roll

Magicawrap-tape

Magicawrap



®First, wrap the Butyl roll as pre-treatment of the Magicawrap. Then, wrap the Magicawrap to squeeze 1-2 minutes to finish

Materials used: Butyl roll

Magicawrap